List of Corrected Errata for ECMA-269

Summary

Following is a summary of the errors detected and corrected in Standard ECMA-269, Services for Computer Supported Telecommunications Applications (CSTA) Phase III, 4th edition.

28 June 2001

1. Clause 6.8.2, Connection Failure, item 3: 2nd bullet list, bullet 2 and the last sentence in item #3. The text "on the call" is removed from the text.

2. Clause 13.1.5.3.4, Switching Function Devices Functional Requirements, item 2. The first sentence is replaced with:

   • "The deviceList parameter may be provided without any devices in the list by providing a single entry in deviceList with a null formatted deviceID (a deviceID with 0 characters)."

3. Clause 16.1.2, Snapshot Device, arrow direction is corrected in header line.

4. Clause C.3.2, Monitor Start PICS, (per 23.1.3.3, item 2), the following text is added to the end of Miscellaneous Characteristics:

   • "Does the switching function accept a Monitor Start service request on a device that is out of service?"

5. Clause C.11.7, Route Request PICS, "calledDevice" is replaced with "routeingDevice".